

POLICE CIRCULAR ORDER No. 44

Copy of Circular No. 1834-B., dated the 1st November 1950, by the Chief Engineer, Roads and Buildings Department, to all Superintending Engineer/Executive Engineers with memo. Copy to the Chief Secretary to the Government of Orissa, Bhubaneswar.

Preparation of annual repair estimates for residential buildings.

When an estimate for annual repairs to a residential building is prepared, the occupant must always be consulted and asked what repairs are considered necessary. Frequently, all the requirements of an occupant cannot be met, but this must be done as far as possible within the amount of allotment available.

At the time of check measurement of works, either the Executive Engineer or the Subdivisional Officer must make a point of seeking occupants and enquiring whether they are satisfied or have any complaints about their residences. If the latter these must be met as far as possible, always bearing in mind that the funds under P.C.B. repairs are very limited.

Manual Reference

Rule 1148 (c)

(Previous Police Circular Order No. 9 of 1950)